


Lead Lined Frames





Galvanneal

Stainless

Tack weld to rabbet to hold in lead

Tack weld to returns to hold in lead



Partial Sleeve

Full Sleeve

Fully leaded available on request
Customer must specify which side the lead is to be on